

Fig. 1 is a schematic diagram of a mechanical assembly. It shows a horizontal shaft (1) passing through a rectangular block (25). The block (25) has a central cutout. A vertical rod (15) passes through this cutout. On the left side of the block, there is a component (25a) that appears to be a spring or a flexible joint. On the right side, there is a component (25b) that looks like a piston or a plunger. To the right of the block, a component (12d) is shown, which is connected to the shaft (1) and has a zigzag line indicating a break or a continuation of the shaft.

FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E




FIG. 3F




FIG. 3G




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14A FIG. 14B




FIG. 15




FIG. 16




FIG. 17






FIG. 18




FIG. 19

